

Photo 11 - Typical tunnel appearance showing seeping water and calcified construction joints.



Photo 1 - Distinct spall in the crown of the tunnel. This feature was described in previous tunnel inspection reports located approximately at STA 2+45. The appearance is generally uncleaned.