



**Photo 3 (10-17-1985) - Compare against the 1955 photograph. As evidenced, the 1983 Mt. Borah earthquake and/or the subsequent blasting above the spillway (1984) apparently did indeed result in some displacement of the adjacent rock face; likely due to the different response of the foundation materials (alluvium vs. bedrock) beneath the Tunnel and Tower. The 1985 construction was reported necessary to remove rocks obstructing Gates #1 & #5**



**Photo 4 (9/28/1988) - Similar view 2 years later. As reported, the reservoir was lowered to make repair to the concrete slab inside the gate chamber caused by rocks scouring the exposed surfaces.**