

Photo 2: Top (9/13/11) – View from the downstream slope of the dam looking in the general direction of the springs flowing into the collection weir.

Bottom (9/13/11) – Reverse view of spring locations looking at the toe of the dam, taken from the middle part of the downed, large tree-trunk indicated by red arrow, above.

